




# Recall Notice

**IDEAL is voluntarily recalling solenoid test leads manufactured in August 2012**

What is Being Recalled? Test leads manufactured in August 2012 and either (i) used on IDEAL solenoid tester model numbers **61-065**, **61-067**, **61-076**, and **61-080**, or (ii) test leads sold separately as model nos. **61-070** and **61-072** (the “Recalled Test Leads”)

Why is There a Recall? The base of the plug on the test leads may not have enough rubber insulating material. This poses a **risk of electrical shock and may cause serious personal injury or death**.

What Should I Do? **Look for the 0812 date code** on IDEAL test leads purchased since August 2012:



**If you have the Recalled Test Leads, IMMEDIATELY STOP USING THEM and DO NOT SELL THEM**

Remedy: Immediately send the Recalled Test Leads back to IDEAL Industries, Inc. at:

IDEAL Tester Replacement  
1375 Park Avenue  
Sycamore, IL 60178

IDEAL will refund your postage costs and provide either free replacement leads or a refund of the value of the leads (your choice).

Tell Your Customers: Please display this Recall Notice in a prominent place, and provide copies of this notice to all of your customers who may have purchased the recalled leads. Please contact IDEAL to obtain more free copies of this notice or for assistance in contacting your customers.

For more information on the recall, please call 1-877-201-9005, visit our website at [www.idealindustries.com](http://www.idealindustries.com) or email us at: [contactus@idealindustries.com](mailto:contactus@idealindustries.com)

**Post Immediately and Provide Copies of This Notice to Your Customers**